Contamination Incident	Type of Contaminant	Source of Contamination	Bureau	U.S. EPA ID	Remarks
		Berkeley County			
A1 AUTO REPAIR	PETRO	UST	BLWM		Site ID # 01173. RBCA Classification 3BF1. Conducting investigation/Risk Assessment.
ANGELS LANDING	PETRO	UST	BLWM		Site ID # 13856. RBCA Classification 2BB3. Monitored Natural Attenuation.
BAKER TIMBER CO	PETRO	UST	BLWM		Site ID # 01104. RBCA Classification 2BB7. Approved Monitored Natural Attenuation (MNA Awaiti.
BERKELEY COUNTY (OLD LANDFILL)	VOC	LF	BLWM	SCD981028095	In assessment phase. Permit # DWP-015.
BERKELEY COUNTY SCHOOL FOOD SERVICE	PETRO	UST	BLWM		Site ID # 16648. RBCA Classification 3BD7. Approved Monitored Natural Attenuation (MNA Awaiti.
BERKELEY ELECTRIC COOP	PETRO	UST	BLWM		Site ID # 01147. RBCA Classification 3BF3. Monitored Natural Attenuation.
BERKELEY SCHOOL BUS SHOP	PETRO	UST	BLWM		Site ID # 01074. RBCA Classification 2BB7. Approved Monitored Natural Attenuation (MNA Awaiti.
BERKELEY SQUARE EXXON 46818	PETRO	UST	BLWM		Site ID # 01092. RBCA Classification 3BF1. Conducting investigation/Risk Assessment.
BIG A CONVENIENCE STORE	PETRO	UST	BLWM		Site ID # 01210. RBCA Classification 1D4. Active corrective action.
BOUNDS PROPERTY	PETRO	UST	BLWM		Site ID # 14906. RBCA Classification 3BF6. Contacted.
BRASON CONST CO INC	PETRO	UST	BLWM		Site ID # 03070. RBCA Classification 2BB7. Approved Monitored Natural Attenuation (MNA Awaiti.
BROWNS AMOCO STATION	PETRO	UST	BLWM		Site ID # 17095. RBCA Classification 2BB7. Approved Monitored Natural Attenuation (MNA Awaiti.
BRYANS SERVICE STATION	PETRO	UST	BLWM		Site ID # 12442. RBCA Classification 2BB3. Monitored Natural Attenuation.
BULLARD PROPERTY	PETRO	UST	BLWM		Site ID # 17477. RBCA Classification 2BB4. Active corrective action.
CAPE ROMAIN CONTRACTORS INC	PETRO	UST	BLWM		Site ID # 13944. RBCA Classification 2BB3. Monitored Natural Attenuation.
CARSONS GROCERY	PETRO	UST	BLWM		Site ID # 16356. RBCA Classification 2BB5. Inactive.
CHARLESTON CITY OF CYPRESS GARDENS	PETRO	UST	BLWM		Site ID # 17064. RBCA Classification 3BD5. Inactive.
CHARLESTON NAVAL WEAPONS STATION BLDG 922	PETRO	UST	BLWM		Site ID # 16401. RBCA Classification 3BF3. Monitored Natural Attenuation.
CHARLESTON NAVAL WEAPONS STATION COMMON TANKS INFO	PETRO	UST	BLWM		Site ID # 01797. RBCA Classification 2AA4. Active corrective action.
CIRCLE K 2705128	PETRO	UST	BLWM		Site ID # 10984. RBCA Classification 2BB1. Conducting investigation/Risk Assessment.
CIRCLE K 2708115	PETRO	UST	BLWM		Site ID # 01182. RBCA Classification 3BF5. Inactive.

Contamination Incident	Type of Contaminant	Source of Contamination	Bureau	U.S. EPA ID	Remarks
CIRCLE K 8110	PETRO	UST	BLWM		Site ID # 01183. RBCA Classification 3BF4. Active corrective action.
CLARKES EXXON	PETRO	UST	BLWM		Site ID # 01251. RBCA Classification 3BD7. Approved Monitored Natural Attenuation (MNA Awaiti.
CLOVERLEAF CARWASH	PETRO	UST	BLWM		Site ID # 03049. RBCA Classification 3BF3. Monitored Natural Attenuation.
CNWS SWMU 10	VOC	STTF	BLWM	SC8170022620	Bldg 930 Otto Fuel Sump. Surficial Aquifer impacted. In postclosure monitoring phase. Site buildings scheduled for demolition during 2008 and cap to be installed over site. Groundwater monitoring will continue.
CNWS SWMU 12	VOC	UST	BLWM	SC8170022620	Former Southside PCP Treatment Area. In monitoring and remediation phases. CMS Phase, ZVI wall/Phyto installed. Annual monitoring to assess PRB/Phyto effectivness and plume delineation. Additional trees planted for phyto. Groundwater monitoring continues.
CNWS SWMU 14	VOC	STTF	BLWM	SC8170022620	Bldg 58 Otto Fuel Sump. Surficial Aquifer impacted. HRC pilot study implemented, postclosure monitoring continues.
CNWS SWMU 16	VOC	LF	BLWM	SC8170022620	Old Southside Landfill. In CMS Phase. No active groundwater monitoring.
CNWS SWMU 17	VOC	UNK	BLWM	SC8170022620	Old Southside Missile and Waste Oil Disposal Area. In CMS phase. No active groundwater monitoring.
CNWS SWMU 18	METALS	OTHER	BLWM	SC8170022620	Former Southside OB/OD Site.Groundwater monitoring program in place.
CNWS SWMU 23	METALS	LF	BLWM	SC8170022620	Old Southside Annex Sanitary Landfill. In RFI phase. Long term monitoring program in place.
CNWS SWMU 24	VOC	UNK	BLWM	SC8170022620	Old Southside Annex Waste Disposal Area. In RFI Phase II. Tracking off-site portion of plume.
CNWS SWMU 3	METALS	LF	BLWM	SC8170022620	Old Northside Landfill. In RFI phase. Long term monitoring program in place.
CNWS SWMU 36	VOC	UNK	BLWM	SC8170022620	Old Southside Hazardous Waste Facility. In CMS phase. Plume migration has triggered additional investigation.
CNWS/BLDG.1025F	PETRO	UST	BOW		In assessment phase.
CNWS/BLDG.314	PETRO	AGT	BOW		In assessment phase.
CNWS/BLDG.324	PETRO	UST	BOW		Site is in assessment phase.
CNWS/BLDG.7	PETRO	UST	BOW		Leak from fuel oil UST. Monitored natural attenuation.
CNWS/BLDG.708	PETRO	UST	BOW		Site is in remediation phase. Fitness Center (BLDG 708)
CNWS/BLDG.724	PETRO	S/L	BOW		In assessment phase.

Contamination Incident	Type of Contaminant	Source of Contamination	Bureau	U.S. EPA ID	Remarks
CNWS/BLDG.790 (UST 930)	PETRO	UST	BOW		Monitored natural attenuation.
CNWS/BLDG.991	PETRO	UST	BOW		Monitored natural attenuation.
COOPERS STORE	PETRO	UST	BLWM		Site ID # 16023. RBCA Classification 2BB4. Active corrective action.
CORNER STOP 43	PETRO	UST	BLWM		Site ID # 01213. RBCA Classification 2BA1. Conducting investigation/Risk Assessment.
COUNTRY STORE	PETRO	UST	BLWM		Site ID # 14025. RBCA Classification 2BB3. Monitored Natural Attenuation.
DFSP/HANAHAN	PETRO	S/L, AGT	BOW		In remediation and monitoring phases. Two private wells impacted.
DICKS STATION 2	PETRO	UST	BLWM		Site ID # 17238. RBCA Classification 2BB4. Active corrective action.
DICKS STATION INC 1	PETRO	UST	BLWM		Site ID # 01221. RBCA Classification 3BF7. Approved Monitored Natural Attenuation (MNA Awaiti.
DUPONT - BERKELEY SITE	VOC, OTHER	S/L	BOW		In assessment phase. Pursuing corrective action. Contaminants disharging to unnamed drainage ditch.
DUPONT - COOPER RIVER PLANT	OTHER	PPL	BOW		Site is in monitoring phase.
ENMARK 350	PETRO	UST	BLWM		Site ID # 10425. RBCA Classification 4BC5. Inactive.
ENMARK 510	PETRO	UST	BLWM		Site ID # 11406. RBCA Classification 2BB3. Monitored Natural Attenuation.
FAST POINT 49	PETRO	UST	BLWM		Site ID # 11816. RBCA Classification 2BB8. Awaiting Funding.
FORMER 7 ELEVEN 11842	PETRO	UST	BLWM		Site ID # 15697. RBCA Classification 3BF1. Conducting investigation/Risk Assessment.
FORMER B&D SELF SERVICE	PETRO	UST	BLWM		Site ID # 01227. RBCA Classification 2BB7. Approved Monitored Natural Attenuation (MNA Awaiti.
FORMER MARSHS BP STATION	PETRO	UST	BLWM		Site ID # 15859. RBCA Classification 3BD1. Conducting investigation/Risk Assessment.
FORMER SERVICE STATION	PETRO	UST	BLWM		Site ID # 17152. RBCA Classification 2BB4. Active corrective action.
GAS MART	PETRO	UST	BLWM		Site ID # 10563. RBCA Classification 3BD1. Conducting investigation/Risk Assessment.
GATES RUBBER COMPANY (FUD)	VOC	UNK	BOW		In remediation.
GEORGIA PACIFIC RESINS	OTHER	S/L	BOW		In remediation.
GETHERS SERVICE STATION	PETRO	UST	BLWM		Site ID # 13857. RBCA Classification 2BB3. Monitored Natural Attenuation.
GOOSE CREEK TEXACO	PETRO	UST	BLWM		Site ID # 01181. RBCA Classification 3BF5. Inactive.

Contamination Incident	Type of Contaminant	Source of Contamination	Bureau	U.S. EPA ID	Remarks
HANAHAN WATER TREATMENT PLANT	PETRO	SPL	BOW		Monitored Natural Attenuation.
HANDY STOP	PETRO	UST	BLWM		Site ID # 11876. RBCA Classification 3AC1. Conducting investigation/Risk Assessment.
HARRYS FISH CAMP	PETRO	UST	BLWM		Site ID # 01249. RBCA Classification 1A1. Conducting investigation/Risk Assessment.
HARVEYS LUCKY DOLLAR	PETRO	UST	BLWM		Site ID # 15913. RBCA Classification 1D4. Active corrective action.
HESS STATION 40372	PETRO	UST	BLWM		Site ID # 11844. RBCA Classification 3BF1. Conducting investigation/Risk Assessment.
HIGHLAND CLEAT & VENEER CO INC	PETRO	UST	BLWM		Site ID # 17999. RBCA Classification 2BB3. Monitored Natural Attenuation.
HILLS LANDING INC	PETRO	UST	BLWM		Site ID # 13996. RBCA Classification 2BB6. Contacted.
HOME TELEPHONE CO INC	PETRO	UST	BLWM		Site ID # 11451. RBCA Classification 2BB3. Monitored Natural Attenuation.
HOT & NOW	PETRO	UST	BLWM		Site ID # 01172. RBCA Classification 2BB7. Approved Monitored Natural Attenuation (MNA Awaiti.
INDUSTRIAL SALES CO INC	PETRO	UST	BLWM		Site ID # 17798. RBCA Classification 2BB3. Monitored Natural Attenuation.
J&W'S CONVENIENCE STORE & GRILL	PETRO	UST	BLWM		Site ID # 15648. RBCA Classification 2BB1. Conducting investigation/Risk Assessment.
JACK FLASH AMOCO	PETRO	UST	BLWM		Site ID # 10481. RBCA Classification 3BF5. Inactive.
JOHN SANDERS JR	PETRO	UST	BLWM		Site ID # 02940. RBCA Classification 2BB4. Active corrective action.
KAWASAKI CLEANERS	VOC	S/L	BLWM	SCS123457053	BLWM File # 56160. No activity at this time.
KLASSY KORNER BOUTIQUE	PETRO	UST	BLWM		Site ID # 16975. RBCA Classification 2BB6. Contacted.
L C SMITH GROCERY	PETRO	UST	BLWM		Site ID # 01204. RBCA Classification 2AB4. Active corrective action.
L R GROOMS	PETRO	UST	BLWM		Site ID # 01266. RBCA Classification 3BF6. Contacted.
LAKE MOULTRIE WATER CO INC	PETRO	UST	BLWM		Site ID # 16661. RBCA Classification 2BB7. Approved Monitored Natural Attenuation (MNA Awaiti.
LAKES EXXON	PETRO	UST	BLWM		Site ID # 01255. RBCA Classification 2BB6. Contacted.
LANXESS-BAYER CORPORATION	VOC, BNA, METALS	PPL	BLWM	SCD048373468	In assessment and monitoring phase. EPA Lead. Corrective Measures Study underway.
LEBANON QUICK STOP	PETRO	UST	BLWM		Site ID # 15445. RBCA Classification 2BB7. Approved Monitored Natural Attenuation (MNA Awaiti.
MACEDONIA SUPERETTE	PETRO	UST	BLWM		Site ID # 14143. RBCA Classification 2BB7. Approved Monitored Natural Attenuation (MNA Awaiti.

Contamination Incident	Type of Contaminant	Source of Contamination	Bureau	U.S. EPA ID	Remarks
MACKS CAMP	PETRO	UST	BLWM		Site ID # 01253. RBCA Classification 1D8. Awaiting Funding.
MAGIC NAIL DBA BIG T'S	PETRO	UST	BLWM		Site ID # 01184. RBCA Classification 5B1. Conducting investigation/Risk Assessment.
MARTINS GROCERY	PETRO	UST	BLWM		Site ID # 01258. RBCA Classification 2BB1. Conducting investigation/Risk Assessment.
MONCKS CORNER MAINTENANCE FACILITY	PETRO	UST	BLWM		Site ID # 01076. RBCA Classification 3BD5. Inactive.
O J STROBEL OIL CO	PETRO	UST	BLWM		Site ID # 03063. RBCA Classification 3BF1. Conducting investigation/Risk Assessment.
OASIS ONE STOP	PETRO	UST	BLWM		Site ID # 10312. RBCA Classification 2BB3. Monitored Natural Attenuation.
OLD CHARLIES TACKLE & BAIT	PETRO	UST	BLWM		Site ID # 10752. RBCA Classification 3BF7. Approved Monitored Natural Attenuation (MNA Awaiti.
PANTRY 330	PETRO	UST	BLWM		Site ID # 01201. RBCA Classification 3BF3. Monitored Natural Attenuation.
PANTRY 3870 DBA KANGAROO EXPRESS	PETRO	UST	BLWM		Site ID # 01189. RBCA Classification 3BF1. Conducting investigation/Risk Assessment.
PANTRY 3871 DBA KANGAROO EXPRESS	PETRO	UST	BLWM		Site ID # 10038. RBCA Classification 3BA2. Free Product recovery only.
PANTRY 3885 DBA KANGAROO EXPRESS	PETRO	UST	BLWM		Site ID # 11339. RBCA Classification 3BF7. Approved Monitored Natural Attenuation (MNA Awaiti.
PANTRY 446	PETRO	UST	BLWM		Site ID # 01202. RBCA Classification 2BB1. Conducting investigation/Risk Assessment.
PANTRY 448	PETRO	UST	BLWM		Site ID # 03056. RBCA Classification 3BA2. Free Product recovery only.
PATS CASH GROCERY	PETRO	UST	BLWM		Site ID # 01250. RBCA Classification 2BB4. Active corrective action.
PILOT TRAVEL CENTER 064	PETRO	UST	BLWM		Site ID # 03074. RBCA Classification 2BA2. Free Product recovery only.
PINEVILLE SELF SERVICE	PETRO	UST	BLWM		Site ID # 11521. RBCA Classification 2BB4. Active corrective action.
PORT UNIT 263	PETRO	UST	BLWM		Site ID # 01216. RBCA Classification 3BD3. Monitored Natural Attenuation.
PRIDE GAS STATION	PETRO	UST	BLWM		Site ID # 01205. RBCA Classification 2BB3. Monitored Natural Attenuation.
QUICK PANTRY 14	PETRO	UST	BLWM		Site ID # 03024. RBCA Classification 3BA8. Awaiting Funding.
R FOOD MART	PETRO	UST	BLWM		Site ID # 15338. RBCA Classification 1D1. Conducting investigation/Risk Assessment.
R THORNLEY	PETRO	UST	BLWM		Site ID # 01220. RBCA Classification 4BC8. Awaiting Funding.
RELIABLE ELECTRIC FACILITY	VOC	S/L, AGT	BOW		In remediation phase.

Contamination Incident	Type of Contaminant	Source of Contamination	Bureau	U.S. EPA ID	Remarks
ROYLE ROAD ASSOCIATES PROPERTY	PETRO	UST	BLWM		Site ID # 14496. RBCA Classification 3BF5. Inactive.
SAMS SERVICE CENTER	PETRO	UST	BLWM		Site ID # 17066. RBCA Classification 2BB6. Contacted.
SANTEE COOPER - JEFFERIES	METALS	PPL	BOW		Site is in monitoring phase.
SCA-CHARLESTON DISPOSAL	VOC	LF	BLWM	SCD981028525	BLWM File # 20089. In monitoring and remediation phases.
SCOTCHMAN 168 DBA PACIFIC PRID	PETRO	UST	BLWM		Site ID # 01191. RBCA Classification 3BF7. Approved Monitored Natural Attenuation (MNA Awaiti.
SCOTCHMAN 82	PETRO	UST	BLWM		Site ID # 01188. RBCA Classification 2BB7. Approved Monitored Natural Attenuation (MNA Awaiti.
SCPSA CROSS GENERATING STATION	METALS	LF	BLWM		In monitoring phase. Groundwater contamination is possibly from naturally occuring metals. Permit # 083337-1601, IWP-186.
SHORT STOP FOOD STORE	PETRO	UST	BLWM		Site ID # 16553. RBCA Classification 3BA5. Inactive.
SMALLS AMOCO	PETRO	UST	BLWM		Site ID # 01243. RBCA Classification 3BF8. Awaiting Funding.
SOUTH CAROLINA PUBLIC SERVICE AUTHORITY	PETRO	UST	BLWM		Site ID # 01112. RBCA Classification 2BB6. Contacted.
SPORTY JOES CONV STORE	PETRO	UST	BLWM		Site ID # 01203. RBCA Classification 3BF8. Awaiting Funding.
ST STEPHEN SECTION SHED	PETRO	UST	BLWM		Site ID # 01075. RBCA Classification 2BB7. Approved Monitored Natural Attenuation (MNA Awaiti.
ST STEPHENS SHELL	PETRO	UST	BLWM		Site ID # 01225. RBCA Classification 3BF5. Inactive.
STATION 1645 LLC	PETRO	UST	BLWM		Site ID # 01212. RBCA Classification 3BF8. Awaiting Funding.
SUNOCO 0616- 1061/COOP2665	PETRO	UST	BLWM		Site ID # 01215. RBCA Classification 2BB3. Monitored Natural Attenuation.
SUNOCO 0622- 1519/COOP2644	PETRO	UST	BLWM		Site ID # 10644. RBCA Classification 3BF7. Approved Monitored Natural Attenuation (MNA Awaiti.
SUNOCO 0627- 8675/COOP2662	PETRO	UST	BLWM		Site ID # 01371. RBCA Classification 3BA5. Inactive.
SUNOCO 0630- 7680/COOP2646	PETRO	UST	BLWM		Site ID # 01218. RBCA Classification 3BF3. Monitored Natural Attenuation.
SUNOCO 0635- 4732/COOP2645	PETRO	UST	BLWM		Site ID # 01217. RBCA Classification 3BF7. Approved Monitored Natural Attenuation (MNA Awaiti.
THORNLEY OIL CO.	PETRO	AGT	BOW		In remediation phase. Groundwater contaminant plume defined - soil removal necessary.
VARNERS E Z MART	PETRO	UST	BLWM		Site ID # 01209. RBCA Classification 3BF5. Inactive.

Contamination Incident	Type of Contaminan	Source of Contamination	Bureau	U.S. EPA ID	Remarks
WANDO GROCERY	PETRO	UST	BLWM		Site ID # 14035. RBCA Classification 2BB1. Conducting investigation/Risk Assessment.
WANDO GROCERY	PETRO	UST	BLWM		Site ID # 14383. RBCA Classification 2BB7. Approved Monitored Natural Attenuation (MNA Awaiti.
WILDWOOD CONVENIENCE	PETRO	UST	BLWM		Site ID # 13053. RBCA Classification 3BB3. Monitored Natural Attenuation.
WRIGHTS GROCERY	PETRO	UST	BLWM		Site ID # 12938. RBCA Classification 2AA4. Active corrective action.
YEAMANS HALL DRYCLEANER	VOC	UNK	BLWM	SCD981867591	In assessment phase. AKA Yeaman's Hall One Hour Martinizing.
YOUMANS SHOP 1	PETRO	UST	BLWM		Site ID # 10217. RBCA Classification 3AC1. Conducting investigation/Risk Assessment.
YOUNGS 645	PETRO	UST	BLWM		Site ID # 12809. RBCA Classification 1D3. Monitored Natural Attenuation.
Total for Berkeley 134					